


Friday, January 20, 2017

CANAL BANK EROSION AND STABILIZATION




Locations where signs would help to reduce canal bank erosion

The locations that are identified are those that could only be seen landside where access was granted by the property owner or viewed from the easement.




Locations in critical need of restoration



Locations in critical need of restoration

- The locations chosen were based on trees falling in canal causing conveyance problems. This criteria is one of the main criteria's used by the SFWMD.
- Many of the properties along the canal system have lost significant amounts of real property due to erosion.
- A list 46 properties have filed complaints of erosion with the Village and/or SFWMD.
- The Village is working with the SFWMD to find the most adequate solution to addressing and funding the bank stabilization issues in Palmetto Bay.
- The only way to inspect all the properties along the 8 miles of canal system is to view from the water side.
- Staff is working with the South Florida Water Management District to tour the entire canal system within Palmetto bay via boat in order to document the condition of the entire canal system.

WHAT WILL THE SIGNS LOOK LIKE AND WHAT WILL THEY SAY?



CANAL INFORMATIONAL SIGNAGE PROGRAM FLOWCHART

*minimum of 10 applications to process
 *no sign shall be within 1000 feet of another
 *applicant must get approval of neighbor to each side of rear neighbor. Total of 2 neighbor signatures

